Stable versions available on our website are marked in red.

Version 3.0.0.7609

Fixes:

- Fixed error causing issues with archive player (VDR-A)

Version 3.0.0.7608

Fixes:

- POS/LPR report function fixes
- Small improvements in POS reports

Version 3.0.0.7607

Fixes:

- Fixes for Thermal POS protocol

Version 3.0.0.7606

Changes:

- Improvements in Canon video analytics

Fixes:

- Fixes for Central server events
- Stability improvements

Version 3.0.0.7605

Changes:

- New library for AL-0408 I/O cards was removed because of stability issues

----

Version 3.0.0.7604

Changes:

- Snapshot support for CMS4

Stable versions available on our website are marked in red.

- VCA events support through HTTP API

Fixes:

- Qt libraries added to backup player

Version 3.0.0.7603

Changes:

- LPR function added to demo version
- Support for JPEG, GIF and SVG files in driver database

Version 3.0.0.7602

Changes:

- New Ganz camera added
- Events database is created automatically during first run of the software (default folder D:\vdrsDatabase)

Version 3.0.0.7601

Changes:

- Changes in COM port configuration

Version 3.0.0.7600

Fixes:

- Fixes of emap folder settings

Version 3.0.0.7581

Changes:

- LPR is now avaiable for free with license for 8 or more cameras (Netstation or NetHybrid)

Fixes:

Stable versions available on our website are marked in red.

- Fixes for local archive support in CMS4
- New library for AL-0408 cards, support for 4 cards in the same PC (only 32bit version)

Version 3.0.0.7580

Changes:

- New Grunding cameras added
- New HTTP API commands for CMS4

Fixes:

- Fixes for Input/Output support in Gruding cameras

Version 3.0.0.7575

Fixes:

- Changes in POS transactions listings