

Bugfixes:

- Fixed AL0804 alarm card detection
- Added missing vcredist_2010 libraries